

DEC 1951 --

U.S. Officials Only  
CONFIDENTIAL

SECURITY INFORMATION

CENTRAL INTELLIGENCE AGENCY  
**INFORMATION REPORT**

COUNTRY Poland

SUBJECT Zaklady Metalowe No 3 Wroclaw: Location/Production,  
Security, Personnel, Panstwowe Zaklady Lotnicze.

50X1-HUM

DATE DISTR. 27 Aug 1953

NO. OF PAGES 3

NO. OF ENCLS. 4

SUPP. TO  
REPORT NO.

50X1-HUM

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE  
OF THE UNITED STATES, WITHIN THE MEANING OF TITLE 18, SECTIONS 793  
AND 794, OF THE U.S. CODE, AS AMENDED. ITS TRANSMISSION OR REVE-  
LATION OF ITS CONTENTS TO OR RECEIPT BY AN UNAUTHORIZED PERSON IS  
PROHIBITED BY LAW. THE REPRODUCTION OF THIS REPORT IS PROHIBITED.

THIS IS UNEVALUATED INFORMATION

Zaklady Metalowe No 3.

1.
2. "For purposes of camouflage the name of this plant gets changed from time to time:
  - In 1949 it was called Fabryka Silnikow Lotniczych 'Fasil'.
  - From 1950 to autumn 1951, Panstwowe Zaklady Lotnicze.
  - From autumn 1951 to January 1953, Wytownia Sprzetu Komunikacyjnego No 3.
  - Since January 1953 [as of May 1953], Zaklady Metalowe No. 3.
3. "It was known in the plant that there were altogether five such plants in Poland.  
No 1 is situated at Okęcie in Warsaw. No 4 is at Bieszczow.
4. "The plant building in Psie Pole is E-shaped and pretty old. It is said to have  
been a former German munitions factory, operated with slave labour. This is  
apparently true as the walls are still covered with inscriptions written by the  
slave workers in all sorts of languages. There are still barracks on the plant  
grounds. They are not used now and are being torn down one by one.

50X1-HUM

50X1-HUM

U.S. Officials Only

CONFIDENTIAL

SECURITY INFORMATION

DISTRIBUTION	STATE	<input checked="" type="checkbox"/> ARMY	<input checked="" type="checkbox"/> NAVY	<input checked="" type="checkbox"/> AIR	<input checked="" type="checkbox"/> FBI	ORR EV	<input checked="" type="checkbox"/>	
--------------	-------	--	--	---	---	--------	-------------------------------------	--

This report is for the use within the USA of the intelligence components of the Departments or  
Agencies indicated above. It is not to be transmitted overseas without the concurrence of the  
originating office through the Assistant Director of the Office of Collection and Dissemination, CIA.

50X1-HUM

SECRET

- 2 -

CONFIDENTIAL

US OFFICIALS ONLY/SECURITY INFORMATION

5. "The grounds are surrounded with a wall which has barbed wire on top and watch towers every 50-60 metres. The towers have machine guns and searchlights which rotate by night. The front of the plant faces the Olechnica highway, and is close to the local railway station. To get to the plant from town one takes the bus from Bij-Zelenski to Bierutowka. A special railway siding leads to it from the station. The plant production is loaded into cars on this siding by night. It is packed in large boxes inscribed with the words: 'Careful! Glass!' Diesel engines which make very little noise are used to move the freight cars.
6. "The plant has 3000 workers, of whom 2000 are civilians, the rest soldiers.
7. [redacted] it produces YAK motors and artillery shells [redacted]  
the plant also makes chronometers, anemometers, petrol gauges for planes and SHL motors for motorcycles.
8. "Almost the entire management and technical staff of the plant is Soviet: colonels, majors, captains, airmen, etc. Only a few are Polish and these are of low rank: only one is a major; the rest are young subalterns.
9. "The entrance of the plant is guarded by industrial guards (Straz Promyslowa). The towers on the walls are manned by the KBW. Every worker has two passes: one for the main entrance and another for his own department. The workers may not enter any departments other than their own. The tools are handed out by special trustees who may circulate from one department to another. There is a special anti-sabotage bureau, the referat wojskowy. As copper is a metal in short supply, the screws were carefully counted. [redacted]
10. "About every tenth worker is searched on leaving the plant. Each worker when he is hired must sign an obligation that for five years after leaving he will keep absolute silence on everything he has seen or heard at the plant. The obligation also states that should he break this promise, he will be tried by a military tribunal for the disclosure of military secrets. Most of the workers at the plant are young people, because the authorities apparently hope that they will be more loyal than the old workers. They are not given any political instruction worth mentioning, but discipline is purely military. [redacted] In January 1952 Soviet norms were introduced. Nobody could earn more than 600 zl. any longer; my wage dropped to 400 zl. [redacted] The other young workers, about 75% of the total work force, got the same idea but were not permitted to leave. [redacted]
11. [redacted]

50X1-HUM

50X1-HUM

50X1-HUM

50X1-HUM

50X1-HUM

ENCLOSURE (A): Layout sketch  
with legendof Zaklady Metalowe No 3

CONFIDENTIAL

US OFFICIALS ONLY/SECURITY INFORMATION

ENCLOSURE (A)


CONFIDENTIAL/US OFFICIALS ONLY/SECURITY INFORMATION

50X1-HUM


## Orientation sketch

partly of a communication equipment plant, now called Zaklady Metalowe No 3 in Wroclaw: Psie Pole, in Poland.

(This plant was called since the autumn 1951 "Wytownia Sprzetu Komunikacyjnego" - communication equipment plant - but in January 1953 certain parts of this plant were renamed into Zaklady Metalowe No 3 (Metal plant No 3))




1. (S) production of main parts of the "YAK" engines
2. (KT) technical control
3. (OKT) Final technical control
4. (W) Room for lending tools
5. (TM) Repairs under own management
6. (B) Offices (with the inscription: Zaklady Metalowe Nr 3)
0. Main entrance




1. (S) As on the ground floor
2. (TT) Construction department
3. Archives
4. (Ws) Tool lending room
5. (RW) Military "reterat" (section)
6. (B) Offices
7. Reading and recreation room
8. Unknown

50X1-HUM



1. (M) Assembly hall of engines
2. (PA) Unknown
3. (TN) Tool making hall
4. (T) Room for special workers assigned to supply plans and tools
5. (W) Tool lending room
6. Offices



1. Not yet put into operation (in January 1953)
2. (PN) Production of sparking plugs
3. (PN) Production of magnetos
4. (PP) Precision works
5. (KT) Technical control
6. (B) Offices
7. (OKT) Final technical control

Note: Figures (1,2,...) are used only on this sketch, while letters (n g TN, in parenthesis) are the same as were used in the plant, at least up to January 1953.

CONFIDENTIAL/US OFFICIALS ONLY/SECURITY INFORMATION